

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25

CP3

MAINTENANCE HISTORY PAGE

K13

K7

VACUUM PERFORMANCE

K14

MAINTENANCE HISTORY

DE-
TAIL

DATE

K8

GAS CHARGE/
DISCHARGE
PERFORMANCE

K18

K15

MAINTENANCE HISTORY

DE-
TAIL

DATE

K9

TEMPERATURE
PERFORMANCE

K18

K16

MAINTENANCE HISTORY

DE-
TAIL

DATE

K10

ELECTRICAL
PERFORMANCE

K18

K17

MAINTENANCE HISTORY

DE-
TAIL

DATE

FIG. 27




FIG. 28




FIG. 29




FIG. 30




FIG. 31




FIG. 32




FIG. 33




FIG. 34




FIG. 35




FIG. 36




FIG. 37




FIG. 38
PRIOR ART




FIG. 39
PRIOR ART

